


# 1968-72 Buick A-Body Rear Window Trim Clip Stud Locations

Measurements taken for a 1970 survivor – note there are variations car-to-car



Rust Repair Patch Panels Manufactured In The USA



BeldenSpeed.com